ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	4	Yelahanka Satellite Town

Street ID	Street Name	Significant Landmark
W0251, W0194, W0196, W0208, W0241, W0245, W0249, W	Maheshwaramma Temple Behind Rd, NA	Sanitary Core

Segment No.	Total Length (m)
4/C-W0251/S104131	196.80

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	54.56	77.581362	13.093370	77.581558	13.093825	W0190	W0208
2	87.18	77.582105	13.093005	77.581376	13.093336	RI-S55	W0245
3	55.06	77.582151	13.093545	77.581950	13.093088	W0190	W0208

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of Drain and Concrete Roads in Sanitary Core in ward no 04 Yelahanka new Satellite Town Sub-Division Yelahanka zone	2000000	2014

Year	Type of Work	Other Work Type
2014 - 2015	Others	Drain and Concrete Roads

Tender	Work Details	Job No. / Work Code
Tender	Construction of Drain and Concrete Roads in Sanitary Core in ward no 04 Yelahanka new Satellite Town Sub-Division Yelahanka zone	004-15-000024

Work Order No.	Work Order Date	Period of Extention
EE (YNK D)/E-PMT-4/WO/42/2014-15	08/01/2015	90 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
25/06/2015	24/06/2016	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
K RAVIKUMAR		0.00

Phone No.	E-Mail ID

9880448650

Field Inspection Details

Number of Trees	Any Other Information	Name
4		DAYANANDA
Date of Inspection	**Remarks**	
01/04/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 4 **Ward Name:** Yelahanka Satellite Town **Street ID:** W0251, W0194, W0196, W0208,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	01/04/2017	01/05/2017	COMPLETED
SE	VASU K M	01/04/2017	01/05/2017	COMPLETED
EE	SRINIVAS	01/04/2017	01/05/2017	COMPLETED
AEE	PRAKASH	01/04/2017	01/05/2017	COMPLETED
AE	DAYANANDA	01/04/2017	01/05/2017	COMPLETED
AE	DAYANANDA	01/04/2017	01/05/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 4 **Ward Name:** Yelahanka Satellite Town **Street ID:** W0251, W0194, W0196, W0208,